Mini Bulletin XRX15D Phaser 3300MFP SPAR Release 1.50.00.19 SMP2R2



Release Date: January 6, 2015 Version 1.0

Software Release Details

If your software is higher or equal to the versions listed below no action is needed. Otherwise, please review this bulletin and consider taking actions as suggested.

Component	Version
Firmware	1.50.00.19
NIC	4.03.02
Engine Firmware	1.05.44
PCL5e	6.08.01
PCL6	5.98
PS3	2.19.06

Purpose

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as a criticality level of **IMPORTANT**

OpenSSL MiTM (Man in the middle) vulnerability fix

Installation Notes

Firmware Release File

Release Install File	1.50.00.19 or greater

The SPAR Software is located here: http://www.support.xerox.com/support/phaser-3300mfp/file-download/enus.html?contentId=105441

Installation Instructions are located at

https://www.xrxgsn.com/admin/public/3452/Phaser3300MFP_Firmware_Upgrade_Instructions_CWIS.pdf.

Save the file to a convenient location on your workstation. Unzip the file if necessary.

© 2015 Xerox Corporation. All rights reserved. XEROX® and XEROX and Design®, ColorQube®, and WorkCentre® are trademarks of Xerox Corporation in the United States and/or other countries.