

# Mini Bulletin XR15Q

## WorkCentre 57xx Series

### Release 061.132.225.12000



Release Date: May 7, 2015

Version 1.0

### Software Release Details

**If your software is higher or equal to the versions listed below no action is needed. Otherwise, please review this bulletin and consider taking actions as suggested.**

Component	Version
System Software	061.132.225.12000
Network Controller	061.135.11020
UI	028.071.00045
IOT Pre-Mod Tag Revision	093.073.000
IOT w/Mod Tag 155	095.040.000
SIP	028.080.00028
DADH	025.020.000
Net Controller OS	061.065.11000

### Purpose

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as a criticality level of **IMPORTANT**

- Includes fix for FREAK Vulnerability In OpenSSL (CVE-2015-0204)

### Installation Notes

#### **Firmware Release File**

Release Install File	061.132.225.12000 or greater
----------------------	------------------------------

The SPAR Software and SPAR installation notes are located here:

<http://www.support.xerox.com/support/workcentre-5735-5740-5745-5755/file-download/enus.html?contentId=122838>

Save the file to a convenient location on your workstation. Unzip the file if necessary.

**Read Me First:**

If the device has release **61.130.220.33700** installed, you must install the pre-upgrade patch **CQ286115v1.dlm** (found in the attached .zip file) before upgrading to this new release. If you have any other release installed on your device you do not need this pre-upgrade patch.

Install the patch using the Machine Upgrade web page process, open the zip file and then extract the patch.