

Mini Bulletin XRX15AL Phaser 3610 WorkCentre 3615 Firmware Release PL2-R3

Release Date: Oct 1, 2015



Purpose

This Bulletin is intended **ONLY** for the specific security problem identified below. The problem identified has been rated a criticality level of **IMPORTANT**

SSLv3.0 Poodle Vulnerability (CVE-2014-3566). SSLv3 supports an older encryption method that is no longer considered secure, and is no longer viable for protecting sensitive data in transmission over networks. This could allow a Man-in-The-Middle (MiTM) attack where a person on the network can force a “downgrade” of the session between a client and server to use SSLv3 instead of a more secure protocol such as TLS. Xerox has disabled SSLv3 in the software version available below.

Software Release Details

If your software is higher or equal to the versions listed below no action is needed. Otherwise, please review this bulletin and consider installation of this version.

Model	Phaser 3610	WorkCentre 3615
Firmware version	201508110658	201508110707
Network	80.48	80.48
Link to update	Available here	Available here

Save the file to a convenient location on your workstation. Unzip the file if necessary.

The Installation Instructions are [Available here](#).

NOTES: TLS is always supported (enabled by Default); no selection needed.

If SSLv3 is selected, TLS takes priority but SSLv3 will work.

SSLv1 and SSLv2 are NOT supported at all.