

Mini Bulletin XRX16AD  
 WorkCentre 5735/5740/5745/5755  
 5765/5775/5790  
 SPAR Release 061.132.226.28000

Bulletin Date: Oct 17, 2016



## Purpose

This Bulletin is intended ONLY for the specific security problems identified below. The problems identified has been rated a criticality level of **IMPORTANT**. This release includes OpenSSL 0.9.8zg.

Includes fix for:

- CVE-2015-3196 -- ssl/s3\_clnt.c, when used for a multi-threaded client, writes the PSK identity hint to an incorrect data structure, which allows remote servers to cause a denial of service.
- CVE-2015-3196 -- The TLS protocol 1.2 and earlier, when a DHE\_EXPORT ciphersuite is enabled on a server but not on a client, does not properly convey a DHE\_EXPORT choice, which allows man-in-the-middle attackers to conduct cipher-downgrade attacks, aka the "Logjam" issue.
- CVE-2016-0778 -- The (1) roaming\_read and (2) roaming\_write functions in roaming\_common.c in the client, when certain proxy and forward options are enabled, do not properly maintain connection file descriptors, which allows remote servers to cause a denial of service (heap-based buffer overflow) or possibly have unspecified other impact.

## Software Release Details

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider installation of this version.

Model	WorkCentre 57xx
Firmware version	061.132.226.28000
Link to Software Release	<a href="#">Available here (see Note)</a>
Link to Installation Instructions	<a href="#">Available here</a>

Save the file to a convenient location on your workstation. Unzip the file if necessary.

### NOTE:

The SPAR Software is located here: [https://www.xrxgsn.com/admin/user/spar\\_release.ihtml](https://www.xrxgsn.com/admin/user/spar_release.ihtml).

The SPAR Release code is: **WC57xxSpar**