

# Xerox Security Bulletin XRX15-003

## Cumulative update for Common Criteria Certification

v1.1

06/09/15

### Background

The System Software Versions listed below for the WorkCentre 3655 and WorkCentre 6655 are cumulative updates that incorporate security vulnerability fixes up through 28 January 2015 as well as other non-security related defect fixes. These releases are Common Criteria certified (see <http://www.xerox.com/information-security/common-criteria-certified/enus.html>).

The system software releases for the products listed below are designed to be installed by the customer. Please follow the procedures contained in the bulletin to install the solution. The system software versions are full system releases so the patch criticality rating is not applicable.

These software releases are compressed into zip files and can be accessed via the links below or via the links on [www.xerox.com/security](http://www.xerox.com/security).

#### WorkCentre 3655:

<http://www.support.xerox.com/support/workcentre-3655/file-download/enus.html?operatingSystem=win7x64&fileLanguage=en&contentId=130911&from=downloads&viewArchived=false>

#### WorkCentre 6655:

<http://www.support.xerox.com/support/workcentre-6655/file-download/enus.html?operatingSystem=win7x64&fileLanguage=en&contentId=130913&from=downloads&viewArchived=false>

### Applicability

The system software release applies to network-connected versions only of the following products:

#### WorkCentre®

3655

6655

## Install Instructions

### Summary of versions and actions:

- Determine the current System Software version or ESS Controller Version on your device for the affected product by printing a Configuration Report following the instructions for printing a Configuration Report in the applicable System Administrator Guide.
- Based on the current System Software version or ESS Controller Version on your device, determine from the table below what action(s) , if any, have to be taken before this release can be installed.
- Perform the indicated action(s) to get your device ready to install this release.
- Once your device is ready to install this release, follow the instructions after the table below under [Release Installation Methods](#) to install this release.

#### For WorkCentre 3655

	If Your Software Version Is System SW Controller	Ready for Release?	Next Step:	System SW / Network Controller Will Now Show:
1	072.060.034.16810	This version of software is currently installed	N/A	072.060.034.16810 / 072.064.16800
2	Greater than 072.060.034.16810	No	Contact Xerox Technical Support to have device downgraded to 072.060.034.16810	072.060.034.16810 / 072.064.16800

#### For WorkCentre 6655

	If Your Software Version Is System SW Controller	Ready for Release?	Next Step:	System SW / Network Controller Will Now Show:
2	072.110.044.20510	This version of software is currently installed	N/A	072.110.044.20510 / 072.114.20500
3	Greater than 072.110.044.20510	No	Contact Xerox Technical Support to have device downgraded to 072.110.044.20510	072.110.044.20510 / 072.114.20500

## Release Installation Methods

This release can and should be installed by the customer. There are a variety of methods available for this.

- Send an Upgrade file to the device using the device web page for Machine Software Upgrade method.
- Upgrade a single device using an LPR command.
- Upgrade several devices using a batch of LPR commands.
- Use XDM and CentreWare Web to send Upgrade files to several devices.

For additional information on the above methods, refer to Customer Tip “How to Upgrade, Patch or Clone Xerox Multifunction Devices” (<http://www.office.xerox.com/support/dctips/dc06cc0410.pdf>).

## Machine Software (Upgrade) Method

- 1) Extract the applicable DLM file (**WorkCentre\_3655-system-sw#07206003416810#.DLM** or **WorkCentre\_6655-system-sw#07211004420510#.DLM**) from the applicable zip file (**WC3655\_sw07206003416810.zip** or **WC6655-system-sw07211004420510.zip**, respectively).
- 2) Open a web browser and connect to the multifunction device by entering the IP number of the device.
- 3) Select the “Index” icon in the upper right portion of the screen.
- 4) Select “Manual Upgrades”
- 5) Enter the User Name and Password of the device.
- 6) Under “Machine Software” select “Upgrades” click the “Enable” box, and click on the “Apply” button to save the change.
- 7) Under “Machine Software” click on “Manual Upgrade”
- 8) Under “Manual Upgrade,” select the Browse button to find and select the applicable file (**WorkCentre\_3655-system-sw#07206003416810#.DLM** or **WorkCentre\_6655-system-sw#07211004420510#.DLM**).
- 9) Select the “Install Software” button.
- 10) All WorkCentres will automatically reboot in order to install the release. The release is installed when the system software version shows the new system software version number.

## Disclaimer

The information provided in this Xerox Product Response is provided “as is” without warranty of any kind. Xerox Corporation disclaims all warranties, either express or implied, including the warranties of merchantability and fitness for a particular purpose. In no event shall Xerox Corporation be liable for any damages whatsoever resulting from user’s use or disregard of the information provided in this Xerox Product Response including direct, indirect, incidental, consequential, loss of business profits or special damages, even if Xerox Corporation has been advised of the possibility of such damages. Some states do not allow the exclusion or limitation of liability for consequential damages so the foregoing limitation may not apply.

©2015 Xerox Corporation. All rights reserved. Contents of this publication may not be reproduced in any form without permission of Xerox Corporation. XEROX®, XEROX and Design®, CentreWare®, Phaser®, ColorQube®, Document Centre®, WorkCentre®, and WorkCentre Pro® are trademarks of Xerox Corporation in the United States and/or other countries. Adobe® and PostScript® are registered trademarks or trademarks of Adobe Systems, Incorporated. All other trademarks are the property of their respective manufacturers.

The information in this bulletin is subject to change without notice.