

Mini Bulletin XRX16I Phaser 6280 Firmware Release PL2-R6

Bulletin Date: Mar 01, 2016



Purpose

This Bulletin is intended ONLY for the specific security problems identified below. The problems identified has been rated a criticality level of **IMPORTANT**. This release includes OpenSSL 0.9.8k.

Includes fix for:

- SSLv3.0 Poodle Vulnerability (CVE-2014-3566). SSLv3 supports an older encryption method that is no longer considered secure, and is no longer viable for protecting sensitive data in transmission over networks. This could allow a Man-in-The-Middle (MiTM) attack where a person on the network can force a “downgrade” of the session between a client and server to use SSLv3 instead of a more secure protocol such as TLS.

Fixed by disabling SSL and using TLS only.

Software Release Details

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider installation of this version.

Model	Workcentre 6280
Firmware version	201511121107
Link to Software Release	Available here
Link to Installation Instructions	Available here

Save the file to a convenient location on your workstation. Unzip the file if necessary.

Important Note: Please read before installing firmware

TLS is always supported (enabled by Default), no selection.
If SSLv3 is selected, TLS takes priority, but SSLv3 will work.
SSLv1 and v2 are NOT supported at all.