

# Mini Bulletin XRX14B ConnectKey Products



## WorkCentre 78xx,58xx,72xx Series ColorQube 93xx Series and ColorQube 8700/8900 Release 071.xxx.034.06000

Release Date: June 19, 2014

Version 1.1

### Software Release Details

System Software	CQ 8700/8900	CQ 93xx	WC 58xx
System Software	071.161.034.06000	071.180.034.06000	071.190.034.06000
Network Controller	071.164.06010.LL	071.184.06010.LL	071.194.06010.LL
User Interface	071.164.06010	071.184.06010	071.194.06010
Marking Engine	004.002.038	020.011.014	096.050.000
Copy Controller	071.164.06010	071.184.06010	071.194.06010
Document Feeder	010.061.000	025.021.048	110.011.016
Fax	003.010.032	003.010.032	003.010.032
Scanner	030.187.000	040.173.000	002.088.000
Software Upgrade	160.116.00251	180.116.00252	190.116.00293

System Software	WC 7220/7225	WC 7830/7835	WC 7845/7855
System Software	071.030.034.06000	071.010.034.06000	071.040.034.06000
Network Controller	071.034.06010.LL	071.014.06010.LL	071.044.06010.LL
User Interface	071.034.06010	071.014.06010	071.044.06010
Marking Engine	018.001.000	090.028.000	090.078.000
Copy Controller	071.034.06010	071.014.06010	071.044.06010
Document Feeder	012.003.000	012.003.000	007.010.000
Fax	003.010.032	003.010.032	003.010.032
Scanner	010.056.085	004.056.085	008.056.085
Software Upgrade	030.116.00252	010.116.00252	010.116.00252

### Purpose

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as **important**:

- Using Program Next Job for Embedded Fax, the previous recipient is not cleared.

## Installation Notes

### Firmware Release File

Release Install File	071.xxx.034.06000 or higher
----------------------	-----------------------------

The SPAR Software and installation notes are located here:

[87xx/89XXsoftware](#)

[93xxsoftware](#)

[58xxsoftware](#)

[72xxsoftware](#)

[7830-35software](#)

[7845-55software](#)

Save the file to a convenient location on your workstation. Unzip the file if necessary.