# Mini Bulletin XRX150 WorkCentre 56xx '08 SBC Release 25.054.065.260



Release Date: May 4, 2015 Version 1.0

## Software Release Details

If your software is higher or equal to the versions listed below no action is needed. Otherwise, please review this bulletin and consider taking actions as suggested.

Component	Version
System Software	25.054.065.260
Network Controller	061.065.11210
UI	25.061.090
IOT	92.009.003
SIP	25.059.024
Fax	003.010.004
Scanner	4.22 (65/75ppm)
	17.05 (32/55ppm)

# **Purpose**

This Bulletin is ONLY intended for the specific security problem(s) identified below. The problem(s) identified has been rated as a criticality level of **IMPORTANT** 

• Includes fix for glibc (Ghost) vulnerability

### **Installation Notes**

#### Firmware Release File

Release Install File	25.054.065.260 or greater

#### The SPAR Software and installation notes are located here:

 $\underline{http://www.support.xerox.com/support/workcentre-5632-5638/file-download/engb.html?contentId=74036}$ 

Save the file to a convenient location on your workstation. Unzip the file if necessary.

## **Read Me First:**

If you have a machine at a System Software version lower than 25.054.040.035 please install **XSA\_56xx08\_Pre-upgradePatch.dlm** included with this software. This must be installed prior to this system upgrade. If your machine is at System Software version 25.054.040.035 or above, you <u>DO NOT</u> need the pre-upgrade patch.

Note: If your machine is alt-booted by Xerox Service to System Software version 25.054.040.035 or above, you <u>DO NOT</u> need the pre-upgrade patch.