


Xerox Product Security Mini Bulletin XR15AU Phaser 6600 / WorkCentre 6605 Spar Firmware Release PL3-R1

Release Date: November 11, 2015



Purpose

This Bulletin is intended **ONLY** for the specific security problem identified below. The problem identified has been rated a criticality level of **IMPORTANT**

Includes fix for:

- SSLv3.0 Poodle Vulnerability (CVE-2014-3566). SSLv3 supports an older encryption method that is no longer considered secure, and is no longer viable for protecting sensitive data in transmission over networks. This could allow a Man-in-The-Middle (MiTM) attack where a person on the network can force a “downgrade” of the session between a client and server to use SSLv3 instead of a more secure protocol such as TLS.

Fixed by implementing a change to default SSL to off and use TLS only.

Software Release Details

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider installation of this version.

Model	Phaser 6600	WorkCentre 6605
Firmware version	201509031021	201509031026
Link to update	Available here	Available here

Completely unzip the file to a known location on your workstation/computer.

The Installation Instructions for both products are [Available here](#).

Note

1. TLS is always supported (enabled by default), no selection.
If SSLv3 is selected, TLS takes priority but SSLv3 will work.
SSLv1 and v2 are **NOT** supported at all.