

Mini Bulletin XRX17AD

Xerox[®] Phaser[®] 3635MFP General Release 20.107.01.000

Bulletin Date: September 28, 2017

Purpose

This Bulletin is intended ONLY for the specific security problem identified below. The problem identified has been rated a criticality level of **IMPORTANT**. This software release has OpenSSL 1.1.0c.

This is a general release that incorporates fixes from previous SPAR releases as well as new fixes not included in previous releases. This general release includes fixes for:

- Removal of IDEA from Embedded Web Server Available Ciphers List to address Sweet32 vulnerability
- Multiple LibTiff CVEs
- ietf-IPv6 CVE-2016-10142 where an attacker can leverage the generation of IPv6 atomic fragments to trigger the use of fragmentation in an arbitrary IPv6 flow and can subsequently perform any type of fragmentation-based attack against legacy IPv6 nodes
- Removal of SSLv3 and inclusion of independent TLSv1.0, TLSv1.1 and TLS1.2 'Enable/Disable' checkboxes
- Fix for OpenSSL Memory Leak CVE-2016-6304 that can cause a denial of service

Software Release Details

If your software is higher or equal to the versions listed below no action is needed. Otherwise, please review this bulletin and consider installation of this version.

Model	Phaser 3635MFP
System SW version	20.107.01.000
Link to Update	Available here
Installation Instructions	Available here (See Section 18)

Save the file to a convenient location on your workstation. Unzip the file if necessary.

