

# Mini Bulletin XR18M

## Xerox® WorkCentre® 3215/3225

### Firmware Release 3.50.02.10-SMP2R1

Bulletin Date: April 20, 2018

#### Purpose

This Bulletin is intended ONLY for the specific security problem identified below. The problems identified have been rated a criticality level of IMPORTANT.

Includes the following:

- Support for SMBv3 as a standalone version, and allow the user to turn off SMBv1 and SMBv2

#### Software Release Details

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider installation of this version.

Model	WorkCentre 3215	WorkCentre 3225
System SW version	3.50.02.10	3.50.02.10
Link to SW update.	<a href="#">Available here</a>	<a href="#">Available here</a>
Link to Install Instr.	<a href="#">Available here</a>	<a href="#">Available here</a>

© 2018 Xerox Corporation. All rights reserved. Xerox®, Xerox and Design®, and WorkCentre® are trademarks of Xerox Corporation in the United States and/or other countries. BR21060  
Other company trademarks are also acknowledged.

