## Mini Bulletin XRX18S Xerox<sup>®</sup> Phaser<sup>®</sup> 3635MFP SPAR Release 20.107.10.000

Bulletin Date: May 4, 2018

## **Purpose**

This Bulletin is intended ONLY for the specific security problem identified below. The problems identified have been rated a criticality level of IMPORTANT.

Includes the following:

 Support for SMBv3 as a standalone version. If the server doesn't support SMBv3, the device will fall back to SMBv1.

## **Software Release Details**

If your software is higher or equal to the versions listed below no action is needed.

Otherwise, please review this bulletin and consider installation of this version.

Model	Phaser 3635MFP
System SW version	20.107.10.000
Link to SW update.	Available here
Link to Install Instr.	Available here

© 2018 Xerox Corporation. All rights reserved. Xerox®, Xerox and Design®, and WorkCentre® are trademarks of Xerox Corporation in the United States and/or other countries. BR21060 Other company trademarks are also acknowledged.

