

# Mini Bulletin XRX21D

Xerox® Phaser® 6510

Xerox® WorkCentre® 6515\*\*

Xerox® VersaLink® B400\* / B405\*\* / B600\* / B605\*\* / B610\* / B615\*\* / B70xx\*\* / C400\* / C405\*\*\* / C500\* / C505\*\* / C600\* / C605\*\* / C7000\* / C70xx\*\*\* / C8000 / C9000

\*Printer \*\*Multifunction Printer \*\*\*Color Multifunction Printer  
SPAR Release xx.65.51 (PL7-R3)

Bulletin Date: March 4, 2021

## Purpose

This Bulletin is intended ONLY for the specific security issues identified below which have been rated with a criticality level of IMPORTANT.

This includes a fix for the following:

- Command injection

## Software Release Details

Please review this bulletin and consider installation of these versions.

Note: If your software is higher or equal to the versions listed below no action is needed.

Model	Phaser 6510	WorkCentre 6515
System SW version (Bridge Release)	64.59.11	65.59.11
Link to SW update and Install Instr. (Bridge Release)	<a href="#">Available here</a>	<a href="#">Available here</a>
Windows Installer v5.3.6.19 (Bridge Release)	<a href="#">Available here</a>	<a href="#">Available here</a>
Mac Installer (Bridge Release)	<a href="#">Available here</a>	<a href="#">Available here</a>
System SW version	64.65.51	65.65.51
Link to SW update and Install Instr.	<a href="#">Available here</a>	<a href="#">Available here</a>
Windows Installer v5.3.6.19	<a href="#">Available here</a>	<a href="#">Available here</a>
Mac Installer	<a href="#">Available here</a>	<a href="#">Available here</a>



Model	VersaLink B400	VersaLink B405	VersaLink B600/B610	VersaLink B605/B615
System SW version (Bridge Release)	37.59.01	38.59.01	32.59.01	33.59.01
Link to SW update and Install Instr. (Bridge Release)	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>
System SW version	37.65.51	38.65.51	32.65.51	33.65.51
Link to SW update and Install Instr.	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>

Model	VersaLink B7025/30/35	VersaLink C400	VersaLink C405	VersaLink C500/C600
System SW version (Bridge Release)	58.59.11	67.59.01	68.59.01	61.59.01
Link to SW update and Install Instr. (Bridge Release)	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>
System SW version	58.65.51	67.65.51	68.65.51	61.65.51
Link to SW update and Install Instr.	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>

Model	VersaLink C505/C605	VersaLink C7000	VersaLink C7020/25/30	VersaLink C8000/C9000	VersaLink C8000W
System SW version (Bridge Release)	62.59.01	56.59.01	57.59.01	70.59.01	N/A
Link to SW update and Install Instr. (Bridge Release)	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	N/A
System SW version	62.65.51	56.65.51	57.65.51	70.65.51	72.65.51
Link to SW update and Install Instr.	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>	<a href="#">Available here</a>

Unzip the file to a known location on your workstation/computer.

## Acknowledgement

Xerox would like to thank the Airbus security team for informing us of the need to address the security issue.

