Mini Bulletin XRX210

Xerox[®] PrimeLink[®] C9065/C9070 SPAR Release 85.6.63

Bulletin Date: August 3, 2021

Purpose

This Bulletin is intended ONLY for the specific security issues identified below which have been rated with a criticality level of IMPORTANT.

Includes a fix for the following:

TCP Port 3000 has been closed

Software Release Details

Please review this bulletin and consider installation of this version.

Note: If your software is higher or equal to the version listed below no action is needed.

Model	PrimeLink C9065/C9070
System SW version	85.6.63
Link to SW	Available here

Unzip the file to a known location on your workstation/computer.

