

Mini Bulletin XR21R

Xerox® Phaser® 6510*

Xerox® WorkCentre® 6515**

Xerox® VersaLink® B400* / B405** / B600* / B605** / B610* / B615** / B70xx** / C400* / C405*** / C500* / C505** / C600* / C605** / C7000*** / C70xx*** / C8000* / C8000W* / C9000*

*Printer **Multifunction Printer ***Color Multifunction Printer

SPAR Release xx.66.91 (PL7-R5)

Bulletin Date: September 17, 2021

Purpose

This Bulletin is intended ONLY for the specific security issues identified below which have been rated with a criticality level of IMPORTANT.

This includes a fix for the following:

- Scanning the printer with NMAP shows TCP port 3000 is open

Software Release Details

Please review this bulletin and consider installation of these versions.

Note: If your software is higher or equal to the versions listed below no action is needed.

Model	Phaser 6510	WorkCentre 6515
System SW version (Bridge Release)	64.59.11	65.59.11
Link to SW update and Install Instr. (Bridge Release)	Available here	Available here
Windows Installer v5.3.6.19 (Bridge Release)	Available here	Available here
Mac Installer (Bridge Release)	Available here	Available here
System SW version	64.66.91	65.66.91
Link to SW update and Install Instr.	Available here	Available here
Windows Installer v5.3.6.19	Available here	Available here
Mac Installer	Available here	Available here



Model	VersaLink B400	VersaLink B405	VersaLink B600/B610	VersaLink B605/B615
System SW version (Bridge Release)	37.59.01	38.59.01	32.59.01	33.59.01
Link to SW update and Install Instr. (Bridge Release)	Available here	Available here	Available here	Available here
System SW version	37.66.91	38.66.91	32.66.91	33.66.91
Link to SW update and Install Instr.	Available here	Available here	Available here	Available here

Model	VersaLink B7025/30/35	VersaLink C400	VersaLink C405	VersaLink C500/C600
System SW version (Bridge Release)	58.59.11	67.59.01	68.59.01	61.59.01
Link to SW update and Install Instr. (Bridge Release)	Available here	Available here	Available here	Available here
System SW version	58.66.91	67.66.91	68.66.91	61.66.91
Link to SW update and Install Instr.	Available here	Available here	Available here	Available here

Model	VersaLink C505/C605	VersaLink C7000	VersaLink C7020/25/30	VersaLink C8000/C9000	VersaLink C8000W
System SW version (Bridge Release)	62.59.01	56.59.01	57.59.01	70.59.01	N/A
Link to SW update and Install Instr. (Bridge Release)	Available here	Available here	Available here	Available here	N/A
System SW version	62.66.91	56.66.91	57.66.91	70.66.91	72.66.91
Link to SW update and Install Instr.	Available here	Available here	Available here	Available here	Available here

Unzip the file to a known location on your workstation/computer.

